

**Customer:** DeKalb County

**Location:** Doraville, GA

**Time & Duration:** 30 Days

**Technical Description:** Service Call

**Technologies:** CPU314

Reference: Dekalb County 14-421 / 1.1.1



## Service call

Customer has a performance problem with existing Siemens CPU314

## Solution

- Replacement of a Siemens CPU with a newer version of 314
- Installation of 64 SD Card to load the program back to the PLC.
- Took offline copy and converted it to new hardware and downloaded it to PLC.
- Deleted one byte in DB2 to get it to compile and download.

---

### MEXICO

INP Mexico S.A de C.V  
Fray Junipero Serra #2450  
Suite 501  
Pabellón Cooperativo Juriquilla  
76230 Queretaro  
Mexico

Tel. +52 442 3930703  
mexico@inp-e.com

### USA

INP North America Inc.  
11390 Old Roswell Rd.  
Suite 126  
Alpharetta, GA 30009  
USA

Tel. +1 678 527-1400  
Fax +1 678 527-1410  
us@inp-e.com

### CANADA

INP Canada Inc.  
2275 Upper Middle Rd E  
Suite 101  
Oakville, Ontario L6H 0C3  
Canada

Tel. +1 289 291-5264  
canada@inp-e.com